### **Katun Performance<sup>™</sup> Drum Unit Rebuild Kit for use in:**

## Canon imageRUNNER/iR 1730/ADVANCE 400/500-series

### **MFPs**

Katun PN: 43771 • OEM PN: N/A

# Reduce Your Cost-Per-Copy on these Popular Canon Applications!

#### **Benefits:**

- ♦ Improve Profitability by Reducing Your Cost-Per-Copy
- **♦** OEM-Equivalent Quality and Performance
- ◆ Reduce Environmental Waste with an Easy 5-Minute Drum Unit Rebuild Process

NOTE: Detailed, illustrated, step by step instructions can be found online at www.katun.com in the Resources/Install & Rebuild section.



### **Product Characteristics:**

	Metrics	OEM	Katun	Your Price
Part number		Drum Unit: 2773B004AA (GPR-39) – NA/SA 2773B003AA (C-EXV37) – EU/FE	Rebuild Kit: 43771	
Price per/sold in		Priced and sold per drum unit	Priced and sold per rebuild kit	
Kit contents		N/A	(1) OPC Drum (1) Drum Cleaning Blade (1) Charge Roller Cleaning Roller (1) Charge Roller Cleaning Wipe	
Photoreceptor stated yield*	imageRUNNER/iR 1730/i/iF	89,500 copies		
	imageRUNNER/iR 1740/i/iF	100,000 copies		
	imageRUNNER/iR 1750/i/iF	112,000 copies	Same as OEM	
	imageRUNNER/iR ADVANCE 400i/400iF	102,000 copies		
	imageRUNNER/iR ADVANCE 500i/500iF	116,000 copies		
Country of origin		China	China	
OPC Color		Green	Green	

<sup>\*</sup> Actual yield may vary depending on machine applications, machine condition, and usage conditions. NOTE: OEM warranty is for 72,000 pages, but stated yield is higher.

### **Other Katun Products for this Model Series:**

OEM Part Number	Katun Part Number	Description	Your Price
FB6-3405-000	26267	Paper Pickup Roller	
FC6-6661-000	36533	Separation Roller	
FC6-7083-000	26268	Feed/Separation Roller	
FM4-8035-000	43557	Waste Toner Container	

14-02-6675 © 2014 Katun Corporation

